






Toy Products Recall Notifications-2022 report 10

In order to protect consumer legitimate rights, the European Union, USA, Canada, Australia together with other countries in the world has established special notification systems to provide information of products which may cause risk to people health and safety.

A total of 61 notifications of children's toys were declared in EU RAPEX are from **Austria, Croatia, Cyprus, Czechia, Denmark, Finland, France, Germany, Greece, Hungary, Ireland, Italy, Lithuania, Poland, Slovakia, Spain, Sweden and United Kingdom**; 3 notifications in Healthy Canadians official website; 2 notifications in Australian product safety recalls official website; 3 notifications in CPSC official website during the 45th and the 48th week of 2022. Except the notification in Australian product safety recalls official website, in which the original country of toys are not mentioned, **up to 58 notifications of children's toys are from China among all those notifications**. Toys were notified because of Contains or is prone to produce small parts, Phthalates content exceeds the limit level, Boron content exceeds the limit level, etc.

Risk	Notifying country	Regulation / Standard	Notification count	Products	Partial Pictures
Choking Contain or release small parts.	Slovakia Lithuania Germany Poland France Austria The United States Canada	EN 71-1 ASTM F963 SOR/2011-17	13	Plush toy Plastic wind-up toy Music box Soft toy Plastic toy Toy gun Rattle toy Plastic bath toy puzzle	
Chemical Phthalates content exceeds the limit level.	Hungary Poland Cyprus Germany Czechia Lithuania France Italy Slovakia	REACH Regulation	21	Plastic doll Plastic balls Soft toy Fancy dress Balloons Skipping rope	
Choking The seams come easily apart, making the filling accessible.	Croatia The United States Canada	EN 71-1 ASTM F963 SOR/2011-17	5	Soft toy Stuffed toy	

Consumer Testing Technology Co., Ltd.

 E-mail: enquiry@cttlab.com
<http://www.cttlab.com>
Guangdong

 (Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)
 TEL: +86(0)769-8898 9888-884

Zhejiang

 (Yiwu/Ningbo)
 TEL: +86(0)579-8998 6543-800

Fujian

 (Quanzhou/Xiamen)
 TEL: +86(0)595-6809 9099-652

Shanghai

TEL: +86 186 7621 9748

Hong Kong

TEL: +852 3462 2595

Vietnam

 TEL: +84 038 6490 452
 E-mail: vn@cttlab.com
Austria

 TEL: +43 699 1000 3888
 E-mail: eu@cttlab.com
USA

 TEL: +1 562 470 7215
 E-mail: info@act-lab.com



Toy Products Recall Notifications-2022 report 10

Continue:

Risk	Notifying country	Regulation / Standard	Notification count	Products	Partial Pictures
Chemical The migration of boron from the product is too high.	Greece Italy Sweden Poland	EN 71-3	6	Toy slime	
Chemical The amount of nitrosamines released by the balloons is too high.	France Sweden	EN 71-12	2	Water bombs Water balloons	
Microbiological The total count of aerobic mesophilic bacteria in this product's filling liquid is too high.	Finland	Toy Safety Directive	1	Doll's feeding bottle	
Choking, Suffocation Contain or release small parts. Plastic packaging is too thin, may cover the mouth and nose causing suffocate.	Italy	EN 71-1	2	Squeezable toy	

Consumer Testing Technology Co., Ltd.

 E-mail: enquiry@cttlab.com
<http://www.cttlab.com>
Guangdong

 (Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)
 TEL: +86(0)769-8898 9888-884

Zhejiang

 (Yiwu/Ningbo)
 TEL: +86(0)579-8998 6543-800

Fujian

 (Quanzhou/Xiamen)
 TEL: +86(0)595-6809 9099-652

Shanghai

TEL: +86 186 7621 9748

Hong Kong

TEL: +852 3462 2595

Vietnam

 TEL: +84 038 6490 452
 E-mail: vn@cttlab.com
Austria

 TEL: +43 699 1000 3888
 E-mail: eu@cttlab.com
USA

 TEL: +1 562 470 7215
 E-mail: info@act-lab.com



Toy Products Recall Notifications-2022 report 10

Continue:

Risk	Notifying country	Regulation / Standard	Notification count	Products	Partial Pictures
<p>Chemical Choking</p> <p>The battery compartment is easily opened/broken, leaving the button batteries accessible. A child could put them in the mouth, which could cause injury to the child's gastrointestinal tract or choking.</p>	United Kingdom Hungary	EN 62115 EN 71-1	3	LED bath lights Spiky ball Plastic toy	
<p>Chemical Choking</p> <p>The migration of boron from the product is too high. Contain or release small parts.</p>	Finland	EN 71-1 EN 71-3	1	Christmas calendar	
<p>Environment</p> <p>The solders in the toy contain an excessive amount of lead and cadmium.</p>	Czechia	RoHS 2 Directive	1	Battery operated toy	
<p>Damage to hearing</p> <p>The sound pressure level of the bell is too high.</p>	Poland	EN 71-1	1	Push along toy	

Consumer Testing Technology Co., Ltd.

 E-mail: enquiry@cttlab.com
<http://www.cttlab.com>
Guangdong

 (Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)
 TEL: +86(0)769-8898 9888-884

Zhejiang

 (Yiwu/Ningbo)
 TEL: +86(0)579-8998 6543-800

Fujian

 (Quanzhou/Xiamen)
 TEL: +86(0)595-6809 9099-652

Shanghai

TEL: +86 186 7621 9748

Hong Kong

TEL: +852 3462 2595

Vietnam

 TEL: +84 038 6490 452
 E-mail: vn@cttlab.com
Austria


 TEL: +43 699 1000 3888
 E-mail: eu@cttlab.com
USA

 TEL: +1 562 470 7215
 E-mail: info@act-lab.com



Toy Products Recall Notifications-2022 report 10

Continue:

Risk	Notifying country	Regulation / Standard	Notification count	Products	Partial Pictures
<p>Choking, Strangulation Small parts can easily detach; the flexible cord can stretch too long and poses a risk of strangulation.</p>	Finland Ireland	EN 71-1	2	Plush toy Fancy dress	

Referenced web:

- <https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>
- <https://www.cpsc.gov/Recalls>
- <https://recalls-rappels.canada.ca/en/search/site>
- <https://www.productsafety.gov.au/recalls>

Remark: All pictures above are selected from the referenced web.

Consumer Testing Technology Co., Ltd.

E-mail: enquiry@cttlab.com

<http://www.cttlab.com>

Guangdong

(Dongguan/Shenzhen/Huizhou/Guangzhou/Zhongshan)
TEL: +86(0)769-8898 9888-884

Zhejiang

(Yiwu/Ningbo)
TEL: +86(0)579-8998 6543-800

Fujian

(Quanzhou/Xiamen)
TEL: +86(0)595-6809 9099-652

Shanghai

TEL: +86 186 7621 9748

Hong Kong

TEL: +852 3462 2595

Vietnam

TEL: +84 038 6490 452
E-mail: vn@cttlab.com

Austria

TEL: +43 699 1000 3888
E-mail: eu@cttlab.com

USA

TEL: +1 562 470 7215
E-mail: info@act-lab.com



玩具产品召回通报预警—2022年第10期

为了保障消费者的合法权益，欧盟、美国、加拿大、澳大利亚等国均建立了专门的预警通报机制，对不合格的玩具产品进行通报。

2022年第45-48周，欧盟RAPEX通报公布的玩具通报案例共61例，来自奥地利，克罗地亚，塞浦路斯，芬兰，法国，德国，希腊，匈牙利，爱尔兰，意大利，立陶宛，波兰，斯洛伐克，瑞典，英国，丹麦，捷克，西班牙；加拿大卫生部官网3例，澳大利亚产品安全召回官网2例，美国CPSC官网3例。除了澳大利亚产品安全召回官网当中通报案例未指明玩具的原产国外，其它所有的通报案例当中与中国有关高达58例。涉及的通报原因包括含有或易产生小部件，邻苯二甲酸酯含量超标，硼迁移量超标等。更多详情如下：

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
窒息 含有或易产生小部件。	斯洛伐克 立陶宛 德国 波兰 法国 奥地利 美国 加拿大	EN 71-1 ASTM F963 SOR/2011-17	13	毛绒玩具 塑料发条玩具 音乐盒 软体填充玩具 塑料玩具 玩具枪 摇铃玩具 塑料浴室玩具 拼图玩具	
化学 邻苯二甲酸酯含量超标。	匈牙利 波兰 塞浦路斯 德国 捷克 立陶宛 法国 意大利 斯洛伐克	REACH Regulation	21	塑料球 塑料娃娃 软体填充玩具 化装舞会服装 气球 跳绳	
窒息 玩具接缝容易裂开，导致填充物可触。	克罗地亚 美国 加拿大	EN 71-1 ASTM F963 SOR/2011-17	5	软体填充玩具 填充玩具	

中鼎检测技术有限公司

 E-mail: enquiry@cttlab.com
<http://www.cttlab.com>
广东 (东莞、深圳、惠州、广州、中山)
TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)
TEL: +86(0)579-8998 6543-800

福建 (泉州、厦门)
TEL: +86(0)595-6809 9099-652

上海
TEL: +86 186 7621 9748

香港
TEL: +852 3462 2595

越南
TEL: +84 038 6490 452
E-mail: vn@cttlab.com
奥地利
TEL: +43 699 1000 3888
E-mail: eu@cttlab.com
美国
TEL: +1 562 470 7215
E-mail: info@act-lab.com



玩具产品召回通报预警—2022年第10期

续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
化学 产品的硼迁移量过高。	希腊 意大利 瑞典 波兰	EN 71-3	6	玩具史莱姆	
化学 气球释放的亚硝酸含量太高。	法国 瑞典	EN 71-12	2	水炸弹 气球	
微生物 产品填充液中的好氧嗜温细菌总数太高。	芬兰	Toy Safety Directive	1	玩具奶瓶	
窒息 窒息 含有或易产生小部件; 包装的塑料袋太薄, 可能会盖住嘴巴和鼻子, 导致窒息。	意大利	EN 71-1	2	挤压玩具	

中鼎检测技术有限公司

E-mail: enquiry@cttlab.com

<http://www.cttlab.com>
广东 (东莞、深圳、惠州、广州、中山)
 TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)
 TEL: +86(0)579-8998 6543-800

福建 (泉州、厦门)
 TEL: +86(0)595-6809 9099-652

上海
 TEL: +86 186 7621 9748

香港
 TEL: +852 3462 2595

越南
 TEL: +84 038 6490 452
 E-mail: vn@cttlab.com

奥地利
 TEL: +43 699 1000 3888
 E-mail: eu@cttlab.com

美国
 TEL: +1 562 470 7215
 E-mail: info@act-lab.com



玩具产品召回通报预警—2022年第10期

续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
<p>化学窒息 电池舱很容易打开/损坏,使纽扣电池容易接近。孩子可能会把它们放进嘴里,这可能会导致孩子的胃肠道受伤或窒息。</p>	英国 匈牙利	EN 62115 EN 71-1	3	LED浴室灯 尖刺球 塑料娃娃	
<p>化学窒息 产品的搬迁移量过高;小部件容易脱落造成窒息危险。</p>	芬兰	EN 71-1 EN 71-3	1	圣诞日历	
<p>环境 玩具中的焊点中含过量的铅和镉。</p>	捷克	RoHS 2 Directive	1	电池驱动玩具	
<p>听力损伤 产品发出的声压级太高。</p>	波兰	EN 71-1	1	推拉玩具	

中鼎检测技术有限公司

E-mail: enquiry@cttlab.com

<http://www.cttlab.com>

广东 (东莞、深圳、惠州、广州、中山)
TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)
TEL: +86(0)579-8998 6543-800

福建 (泉州、厦门)
TEL: +86(0)595-6809 9099-652

上海
TEL: +86 186 7621 9748

香港
TEL: +852 3462 2595

越南
TEL: +84 038 6490 452
E-mail: vn@cttlab.com

奥地利
TEL: +43 699 1000 3888
E-mail: eu@cttlab.com

美国
TEL: +1 562 470 7215
E-mail: info@act-lab.com



玩具产品召回通报预警—2022年第10期

续:

通报原因	通报国	违反法规/标准	通报数量	涉及产品	部分产品图片
<p>窒息 绞杀 含有或易产生小部件；绳索过长存在缠绕勒死风险。</p>	<p>芬兰 爱尔兰</p>	<p>EN 71-1</p>	<p>2</p>	<p>毛绒玩具 化妆舞会服装</p>	

参考网站:

- <https://ec.europa.eu/safety-gate-alerts/screen/search?resetSearch=true>
- <https://www.cpsc.gov/Recalls>
- <https://recalls-rappels.canada.ca/en/search/site>
- <https://www.productsafety.gov.au/recalls>

备注: 以上图片均来自以上参考网站。

中鼎检测技术有限公司

E-mail: enquiry@cttlab.com

<http://www.cttlab.com>

广东 (东莞、深圳、惠州、广州、中山)
TEL: +86(0)769-8898 9888-884

浙江 (义乌、宁波)
TEL: +86(0)579-8998 6543-800

福建 (泉州、厦门)
TEL: +86(0)595-6809 9099-652

上海
TEL: +86 186 7621 9748

香港
TEL: +852 3462 2595

越南
TEL: +84 038 6490 452
E-mail: vn@cttlab.com

奥地利
TEL: +43 699 1000 3888
E-mail: eu@cttlab.com

美国
TEL: +1 562 470 7215
E-mail: info@act-lab.com